

DTE Energy Monroe Power Plant

Inactive Bottom Ash Impoundment CCR Rule Compliance Project

Annual Inspection Report - 2018

Project Number: 60516675

September 7, 2018

Prepared by:

AECOM

27777 Franklin Road, Suite 2000
Southfield, MI 48034
Tel: 248-204-5900
Fax: 248-204-5901

<http://www.aecom.com/>

Table of Contents

Table of Contents	i
1. Introduction	1
1.1 Introduction.....	1
1.2 Background Information.....	1
1.3 Personnel.....	1
2. Annual Inspection Results.....	2
2.1 2018 Inspections	2
3. Maintenance Activities in 2018	3
3.1 Maintenance Activities.....	3
4. Conclusion and Certification.....	4
4.1 Conclusion.....	4
4.2 Certification.....	4

Appendices

- A. 2018 Annual Inspection Report

1. Introduction

1.1 Introduction

The 2018 Annual Inspection Report (AIR) was prepared by AECOM for the DTE Electric Company (DTE) to summarize the results of the annual inspection of the Monroe Power Plant Inactive Bottom Ash Impoundment. This annual inspection complies with the United States Environmental Protection Agency Coal Combustion Residual Rule (40 CFR 257.73). Under the CCR Rule, the Inactive Bottom Ash Impoundment is an "existing surface impoundment" and must be inspected by a qualified professional engineer on a periodic basis, not to exceed one year.

1.2 Background Information

The inactive Bottom Ash CCR Impoundment area was constructed in the late 1960's by building a perimeter dike to surround a low area of the adjacent Lake Erie; the area south of the plant was removed from the Waters of the United States by an Act of Congress prior to plant construction. CCR materials have been placed and allowed to drain into the pond from the north end of the pond; these materials currently form a delta that extends about 1/3 of the way into the pond.

1.3 Personnel

The annual inspection was performed by Mr. Scott G. Hutsell, P.E., with assistance from DTE personnel. Weekly inspections have been and continue to be performed by DTE's plant personnel.

2. Annual Inspection Results

2.1 2018 Inspections

DTE performed the following visual inspections in 2018:

- The annual inspection on July 31, 2018 (provided in Appendix A)
- Weekly inspections during 2018

The annual and weekly inspections included the embankment crest, exterior slopes of the embankment, discharge structures, and discrete observations of the interior of the basins based on accessibility. In addition to the annual and weekly inspections, the general condition of the site and embankment was visually inspected by DTE on a daily basis.

In general, no sign of vegetative distress or structural issues were observed during the annual inspection on the embankment crest, exterior slopes of the embankment and discharge structure. These structures appeared to be in good condition. Areas of concern are listed below; these conditions do not represent an immediate concern for the safe operation or stability of the Inactive Bottom Ash Impoundment and will be addressed through the closure of the Bottom Ash Impoundment.

- The downslope sides of the Impoundment are heavily vegetated and a thorough inspection of the entire surface area of the impoundment is not practical.
- The downstream side of the spillway is heavily vegetated and flow through the spillway is redirected preferentially due to this vegetation. Flow through the spillway is not impeded due to the vegetation at this time.
- There are two areas along the western side of the berm surrounding area 15 (along the discharge canal) where the rip-rap has slid down the slope; DTE should consider replacing this rip-rap to prevent future erosion of the berm in these areas.

3. Maintenance Activities in 2018

3.1 Maintenance Activities

DTE installed additional security fencing along the northern edge of the Bottom Ash Impoundment in March of 2018.

4. Conclusion and Certification

4.1 Conclusion

The annual inspection did not identify any evidence of structural weakness or instability in the Inactive Bottom Ash Impoundment at DTE's Monroe Power Plant.

Based on the annual inspection results and review of available data (including design documents and weekly inspection documentation) the Bottom Ash Impoundment was designed and constructed with generally accepted good engineering standards. Additionally, the Bottom Ash Impoundment is operated and maintained using generally accepted good engineering practice.


4.2 Certification

Certified by:



Scott G. Hutsell, P.E. Michigan License #43961

Senior Project Manager



CCR Impoundment Inspection Report

Station/Owner Monroe Area 15 Bottom Ash Basin / DTE Energy		County Monroe	State Michigan
Inspected By Scott G. Hutsell, P.E.		Date 07/31/2018	Phone No. 517-505-1301
Type of Impoundment: <input type="checkbox"/> Concrete Gravity <input checked="" type="checkbox"/> Embankment <input type="checkbox"/> <input type="checkbox"/> Concrete Arch <input type="checkbox"/> Stone Masonry <input type="checkbox"/> Concrete Buttress <input type="checkbox"/> Other		Type of Inspection <input checked="" type="checkbox"/> Initial <input type="checkbox"/> Periodic <input type="checkbox"/> Follow up <input type="checkbox"/> Other	Weather <input type="checkbox"/> Wet <input checked="" type="checkbox"/> Dry <input type="checkbox"/> Snow Cover <input type="checkbox"/> Other
Hazard Description The Area 15 Bottom Ash Basin is an 104.48 acre surface impoundment; the northern half is deposited sluiced ash while the southern half contains from 3 to 25 ft of water surrounded by an embankment.		Condition Assessment <input checked="" type="checkbox"/> Satisfactory <input type="checkbox"/> Unsatisfactory <input type="checkbox"/> Poor <input type="checkbox"/> Not rated <input type="checkbox"/> Fair	
Remarks		Actions <input type="checkbox"/> None <input checked="" type="checkbox"/> Maintenance <input checked="" type="checkbox"/> Monitoring <input checked="" type="checkbox"/> Minor Repair <input type="checkbox"/> Engineering	Recommendations <input checked="" type="checkbox"/> Inspection letter <input type="checkbox"/> <input type="checkbox"/> Deficiency letter <input type="checkbox"/> <input type="checkbox"/> EOR notice <input type="checkbox"/> <input type="checkbox"/> Engineering study <input type="checkbox"/> Periodic reinspection <input type="checkbox"/> Inspection by EOR
Pool Level (ft) ~575 ft MSL		Total Precipitation since last inspection n/a	

	Problems	COVER:
UPSTREAM SLOPE/FACE	<input type="checkbox"/> 1. None <input checked="" type="checkbox"/> 2. Vegetation >2" dia. <input checked="" type="checkbox"/> 3. Veg. height >6" <input checked="" type="checkbox"/> 4. High bushes <input checked="" type="checkbox"/> 5. Animal Burrows <input type="checkbox"/> 6. Livestock damage <input type="checkbox"/> 7. Wave Erosion <input type="checkbox"/> 8. Slides <input type="checkbox"/> 9. Depressions <input type="checkbox"/> 10. Bulges <input type="checkbox"/> 11. Cracks <input type="checkbox"/> 12. Spalling <input type="checkbox"/> 13. Scarps <input type="checkbox"/> 14. Sloughing <input type="checkbox"/> 15. Holes <input type="checkbox"/> 16. Undermining <input type="checkbox"/> 17. Displaced joints <input type="checkbox"/> 18. Deteriorated joints <input type="checkbox"/> 19. Exposed reinforcement <input type="checkbox"/> 20. Veg. or sediment in rip rap <input type="checkbox"/> 21. Displaced rip rap <input type="checkbox"/> 22. Sparse rip rap <input type="checkbox"/> 23. Other Erosion <input type="checkbox"/> 24. Other	<input checked="" type="checkbox"/> Vegetation <input checked="" type="checkbox"/> Rip rap <input type="checkbox"/> Concrete <input type="checkbox"/> Asphalt <input type="checkbox"/> Other
	Comments /Action Items The embankments surrounding the Bottom Ash Basin is typically 20' wide at the crest – while the access road is made up of crushed rock and rip-rap the interior sideslopes are heavily vegetated. The southern embankment is a rip-rap separation berm built in 2015.	
	Actions <input checked="" type="checkbox"/> None <input type="checkbox"/> Maintenance <input type="checkbox"/> Monitoring <input type="checkbox"/> Minor Repair <input type="checkbox"/> Engineering	
TOP OF DAM/CREST	<input type="checkbox"/> 1. None <input type="checkbox"/> 2. Vegetation >2" dia. <input type="checkbox"/> 3. Veg. height >6" <input checked="" type="checkbox"/> 4. High bushes <input checked="" type="checkbox"/> 5. Animal Burrows <input type="checkbox"/> 6. Livestock damage <input checked="" type="checkbox"/> 7. Ruts <input type="checkbox"/> 8. Depressions <input type="checkbox"/> 9. Unlevel <input type="checkbox"/> 10. Misalignment <input type="checkbox"/> 11. Signs of overtopping <input type="checkbox"/> 12. Cracks <input type="checkbox"/> 13. Deteriorated joints <input type="checkbox"/> 14. Displaced joints <input type="checkbox"/> 15. Exposed reinforcement <input type="checkbox"/> 16. Settlement <input type="checkbox"/> 17. Scarps <input type="checkbox"/> 18. Spalling <input type="checkbox"/> 19. Sinkholes <input type="checkbox"/> 20. Puddles <input type="checkbox"/> 21. Other	<input checked="" type="checkbox"/> Vegetation <input checked="" type="checkbox"/> Rip rap <input type="checkbox"/> Concrete <input type="checkbox"/> Asphalt <input type="checkbox"/> Other
	Comments /Action Items The embankments surrounding the Bottom Ash Basin are typically 20' wide at the crest; the access road is made up of crushed rock and rip-rap. While the access road is in fairly good condition there are some potholes and ruts along the perimeter. The southern embankment is a rip-rap separation berm built in 2015.	
	Actions <input checked="" type="checkbox"/> None <input type="checkbox"/> Maintenance <input type="checkbox"/> Monitoring <input type="checkbox"/> Minor Repair <input type="checkbox"/> Engineering	

CCR Impoundment Inspection Report

	PROBLEMS				COVER:
DOWNSTREAM SLOPE/FACE	<input type="checkbox"/> 1. None	<input type="checkbox"/> 8. Wetness	<input type="checkbox"/> 15. Sloughs/bulges	<input type="checkbox"/> 22. Displaced joints	<input checked="" type="checkbox"/> Vegetation <input type="checkbox"/> Rip rap <input type="checkbox"/> Concrete <input type="checkbox"/> Asphalt <input type="checkbox"/> Other
	<input checked="" type="checkbox"/> 2. Vegetation >2" dia.\	<input type="checkbox"/> 9. Seepage	<input type="checkbox"/> 16. Depressions	<input type="checkbox"/> 23. Deteriorated joints	
	<input checked="" type="checkbox"/> 3. Veg. height >6"	<input type="checkbox"/> 10. Boils	<input type="checkbox"/> 17. Undercutting	<input type="checkbox"/> 24. Exposed reinforcement	
	<input checked="" type="checkbox"/> 4. High bushes	<input type="checkbox"/> 11. Puddles	<input type="checkbox"/> 18. Rutting/rills	<input type="checkbox"/> 25. Riprap needs attention	
	<input type="checkbox"/> 5. Poor grass cover	<input type="checkbox"/> 12. Erosion	<input type="checkbox"/> 19. Cracks	<input checked="" type="checkbox"/> 26. Veg. or sediment in rip rap	
<input checked="" type="checkbox"/> 6. Animal Burrows	<input type="checkbox"/> 13. Slope instability	<input type="checkbox"/> 20. Scour	<input type="checkbox"/> 27. Other		
<input type="checkbox"/> 7. Livestock damage	<input type="checkbox"/> 14. Scarps	<input type="checkbox"/> 21. Spalling			
	28. Does standing water or seepage contain sediment?			<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> NA	
	29. Is there natural hillside seepage in in embankment area?			<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> NA	
	Describe seepage with regard to quantity and clarity (turbidity). Note changes: None				
	Comments /Action Items Along the outside embankment large trees (1-2' in diameter) are visible. The southern embankment is a rip-rap separation berm built in 2015. Along the western edge of the embankment there are two separate areas where rip-rap has sloughed down the slope (along the discharge canal). DTE should consider replacing rip-rap in this area to prevent future erosion of the berm.				
	Actions <input type="checkbox"/> None <input checked="" type="checkbox"/> Maintenance <input type="checkbox"/> Monitoring <input checked="" type="checkbox"/> Minor Repair <input type="checkbox"/> Engineering				
TOE CONTACT	<input type="checkbox"/> 1. None	<input type="checkbox"/> 8. Wetness	<input type="checkbox"/> 15. Sloughs/bulges	<input type="checkbox"/> 22. Displaced joints	<input checked="" type="checkbox"/> Vegetation <input type="checkbox"/> Rip rap <input type="checkbox"/> Concrete <input type="checkbox"/> Asphalt <input type="checkbox"/> Other
	<input checked="" type="checkbox"/> 2. Vegetation >2" dia.	<input type="checkbox"/> 9. Seepage	<input type="checkbox"/> 16. Depressions	<input type="checkbox"/> 23. Deteriorated joints	
	<input type="checkbox"/> 3. Veg. height >6"	<input type="checkbox"/> 10. Boils	<input type="checkbox"/> 17. Undercutting	<input type="checkbox"/> 24. Exposed reinforcement	
	<input checked="" type="checkbox"/> 4. High bushes	<input type="checkbox"/> 11. Puddles	<input type="checkbox"/> 18. Rutting/rills	<input type="checkbox"/> 25. Riprap needs attention	
	<input type="checkbox"/> 5. Poor grass cover	<input type="checkbox"/> 12. Erosion	<input type="checkbox"/> 19. Cracks	<input type="checkbox"/> 26. Veg. or sediment in rip rap	
<input type="checkbox"/> 6. Animal Burrows	<input type="checkbox"/> 13. Slope instability	<input type="checkbox"/> 20. Scour	<input type="checkbox"/> 27. Other		
<input type="checkbox"/> 7. Livestock damage	<input type="checkbox"/> 14. Scarps	<input type="checkbox"/> 21. Spalling			
	28. Does standing water or seepage contain sediment?			<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> NA	
	Describe seepage with regard to quantity and clarity (turbidity). Note changes: None				
	Comments /Action Items Toe is inaccessible to direct inspection due to heavy vegetation. Portions of the toe of slope that are visible from the south bank and other slopes look to be in good condition.				
	Actions <input checked="" type="checkbox"/> None <input type="checkbox"/> Maintenance <input type="checkbox"/> Monitoring <input type="checkbox"/> Minor Repair <input type="checkbox"/> Engineering				
ABUTMENT CONTACTS	<input type="checkbox"/> 1. None	<input type="checkbox"/> 8. Wetness	<input type="checkbox"/> 15. Sloughs/bulges	<input type="checkbox"/> 22. Displaced joints	<input type="checkbox"/> Vegetation <input type="checkbox"/> Rip rap <input type="checkbox"/> Concrete <input type="checkbox"/> Asphalt <input type="checkbox"/> Other
	<input type="checkbox"/> 2. Vegetation >2" dia.	<input type="checkbox"/> 9. Seepage	<input type="checkbox"/> 16. Depressions	<input type="checkbox"/> 23. Deteriorated joints	
	<input type="checkbox"/> 3. Veg. height >6"	<input type="checkbox"/> 10. Boils	<input type="checkbox"/> 17. Undercutting	<input type="checkbox"/> 24. Exposed reinforcement	
	<input type="checkbox"/> 4. High bushes	<input type="checkbox"/> 11. Puddles	<input type="checkbox"/> 18. Rutting/rills	<input type="checkbox"/> 25. Riprap needs attention	
	<input type="checkbox"/> 5. Poor grass cover	<input type="checkbox"/> 12. Erosion	<input type="checkbox"/> 19. Cracks	<input type="checkbox"/> 26. Veg. or sediment in rip rap	
<input type="checkbox"/> 6. Animal Burrows	<input type="checkbox"/> 13. Slope instability	<input type="checkbox"/> 20. Scour	<input type="checkbox"/> 27. Other		
<input type="checkbox"/> 7. Livestock damage	<input type="checkbox"/> 14. Scarps	<input type="checkbox"/> 21. Spalling			
	Comments /Action Items Not applicable				
	Actions <input checked="" type="checkbox"/> None <input type="checkbox"/> Maintenance <input type="checkbox"/> Monitoring <input type="checkbox"/> Minor Repair <input type="checkbox"/> Engineering				

CCR Impoundment Inspection Report

PRINCIPAL SPILLWAY	OBSERVATIONS				
	<input type="checkbox"/> No Spillway				
	Is spillway control system operating properly?				<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
	PROBLEMS				CHANNEL LINING
<input type="checkbox"/> 1. None	<input type="checkbox"/> 9. Misalignment	<input type="checkbox"/> 16. Undermining	<input type="checkbox"/> 23. Sloughing	<input checked="" type="checkbox"/> Vegetation <input type="checkbox"/> Rip rap <input type="checkbox"/> Concrete <input type="checkbox"/> Asphalt <input type="checkbox"/> Other	
<input type="checkbox"/> 2. Trashguard	<input type="checkbox"/> 10. Joints leaking	<input type="checkbox"/> 17. Voids	<input type="checkbox"/> 24. Scarps		
<input checked="" type="checkbox"/> 3. Debris	<input type="checkbox"/> 11. Joint deterioration	<input type="checkbox"/> 18. Cracks	<input type="checkbox"/> 25. Deteriorated lining		
<input checked="" type="checkbox"/> 4. Obstructed	<input type="checkbox"/> 12. Joint displacement	<input type="checkbox"/> 19. Holes	<input type="checkbox"/> 26. Boils		
<input checked="" type="checkbox"/> 5. Plugged/Clogged	<input type="checkbox"/> 13. Conduit collapsed	<input type="checkbox"/> 20. Spalling	<input type="checkbox"/> 27. Outlet erosion		
<input type="checkbox"/> 6. Gates Damaged	<input type="checkbox"/> 14. Exposed reinforcement	<input type="checkbox"/> 21. Slides	<input type="checkbox"/> 28. Displaced rip rap		
<input type="checkbox"/> 7. Gates leaking	<input type="checkbox"/> 15. Erosion	<input type="checkbox"/> 22. Outlet undercutting	<input type="checkbox"/> 29. Sparse rip rap		
<input type="checkbox"/> 8. Gates Rusted			<input type="checkbox"/> 30. Other		
Comments /Action Items					
Spillway appears to be in good repair although the downstream weir is overgrown with vegetation; there are no control systems so the spillway acts as both principal and emergency.					
Actions <input checked="" type="checkbox"/> None <input type="checkbox"/> Maintenance <input type="checkbox"/> Monitoring <input type="checkbox"/> Minor Repair <input type="checkbox"/> Engineering					
EMERGENCY SPILLWAY	OBSERVATIONS				
	<input type="checkbox"/> No emergency spillway			<input checked="" type="checkbox"/> Same as primary spillway	
	PROBLEMS				CHANNEL LINING
	<input type="checkbox"/> 1. None	<input type="checkbox"/> 5. Joint deterioration	<input type="checkbox"/> 9. Undermining	<input type="checkbox"/> 14. Displaced rip rap	<input type="checkbox"/> Vegetation <input type="checkbox"/> Rip rap <input type="checkbox"/> Concrete <input type="checkbox"/> Asphalt <input type="checkbox"/> Other
<input type="checkbox"/> 2. Debris in channel	<input type="checkbox"/> 6. Joint displacement	<input type="checkbox"/> 10. Voids	<input type="checkbox"/> 15. Sparse rip rap		
<input type="checkbox"/> 3. Gates	<input type="checkbox"/> 7. Exposed reinforcement	<input type="checkbox"/> 11. Cracks	<input type="checkbox"/> 16. Outlet undercutting		
<input type="checkbox"/> 4. Misalignment	<input type="checkbox"/> 8. Erosion	<input type="checkbox"/> 12. Holes	<input type="checkbox"/> 17. Inadequate capacity		
		<input type="checkbox"/> 13. Outlet erosion	<input type="checkbox"/> 18. Other		
Comments /Action Items					
See Principal Spillway Above					
Actions <input checked="" type="checkbox"/> None <input type="checkbox"/> Maintenance <input type="checkbox"/> Monitoring <input type="checkbox"/> Minor Repair <input type="checkbox"/> Engineering					
DRAINS/OUTLET STRUCTURE	Observations				
	1. Is discharge system operating properly?				<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
	2. Valves and operators in good condition?				<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
	3. Walkway in good condition?				<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
	4. Is there any turbidity observed at the outlet?				<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A
	5. Seepage at pipe outlet				<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
	6. No Bottom Drain				<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
	7. Bottom Drain Operable				<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
	8. Subsurface Drain Dry				<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
	9. Subsurface drain muddy flow				<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
	10. Subsurface drain obstructed				<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
	11. Animal guard				<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
	12. other				<input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
	Comments /Action Items				
None					
Actions <input checked="" type="checkbox"/> None <input type="checkbox"/> Maintenance <input type="checkbox"/> Monitoring <input type="checkbox"/> Minor Repair <input type="checkbox"/> Engineering					



Photo 1: Looking north along east access road; note overgrown vegetation on inboard edge of berm.



Photo 2: Looking east downslope at the large rip-rap protecting the berm along Lake Erie.



Photo 3: Looking east from west access road at south separation berm.



Photo 4: Looking west from east access road at south separation berm.



Photo 5: Area along the west berm needing rip-rap replacement due to sloughing into the discharge canal.

